

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

F. & H. BENNING COMPANY
1014 Benning Road
Galesville
Anne Arundel County
Maryland

HAER MD-138

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Todd A Croteau, photographer, 2005

- | | |
|----------|--|
| MD-138-1 | GENERAL VIEW OF FORMER F. & H. BENNING COMPLEX NORTH TOWARDS TENTHOUSE CREEK. THE SHELL MILL WAS LOCATED IN THE BUILDING IN THE FOREGROUND. THE SHUCKING AND PROCESSING WAS DONE IN THE REAR BUILDING. OYSTER BOATS DOCKED WHERE THE CRANES ARE CURRENTLY LOCATED. |
| MD-138-2 | ELEVATION OF FORMER SHELL MILL BUILDING AND SHEDS. |
| MD-138-3 | DETAIL ELEVATION OF FORMER SHELL MILL BUILDING. |
| MD-138-4 | NORTH ELEVATION OF OYSTER SHUCKING BUILDING. SHUCKING TOOK PLACE AT FRONT OF BUILDING WHERE WINDOWS ARE LOCATED. |
| MD-138-5 | BOILER, LOCATED IN BACK ROOM OF OYSTER SHUCKING BUILDING. STEAM WAS USED IN OYSTER PROCESSING, FOR EXAMPLE IN STERILIZING EQUIPMENT. |